## Installing the Quick-Connect® Surface Mount Swivel Turnbuckle



Measure, mark, and drill pilot holes.



Bolt/screw Surface Mount fitting to wall/post (bolts or screws sold separately)




Spin the turnbuckle lock-nut onto the exposed threads. Then attach Quick-Connect® and rotate the body 4 full turns.



4

Stretch cable tight across fitting and mark at Cut Gauge Line.
Cut cable at mark.



Loosen Quick-Connect®
2 full turns and insert cut
cable end as far as it will go
into the fitting; the jaws will
automatically lock on.



Hand tighten the Quick-Connect® as far as possible, then swiftly hit the cable line with your palm several times to ensure that jaws are securely seated.



Use wrenches to tighten the Quick-Connect® to desired final tension.



Tighten the lock-nut against the Quick-Connect® to prevent the fitting from loosening.

