





and 9283-10DC-P

Check and do a test or dry fit with hardware to make sure all dimensions are correct before proceeding with production. Sizes and specifications may change over time.

Print with no scaling for 1:1 Scale